

IN THE DRAWINGS

In Figs. 5-11, members 6, 7, 9, 8, 7, 10 and 6, respectively, were originally shaded to indicate heating. On the attached replacement sheets of these Figs. the shading is replaced zig-zag phantom lines that may suggest heating by zig-zag resemblance to electrical resistance but do not introduce such electrical resistance because in phantom lines.

In Figs. 9-11, more familiar liquid-indicating shading is used for ink 14.



REPLACEMENT SHEET

10/018,302

U 013688-5

1/5




FIG. 1




FIG. 2




FIG. 3




FIG. 4



REPLACEMENT > FILE 1

10/018,302
U 013688-5

2/5




FIG. 5




FIG. 6



OCT 23 2003
PLACEMENT SITE 1
10/018,302
U 013688-5

3/5




FIG. 7




FIG. 8



REPLACEMENT SHEET

10/018,302

U 013688-5

4/5

FIG. 9





FIG. 10





P-PLACEMENT SITE 1
10/018,302
U 013688-5

5/5




FIG. 11